

State Water Resources Control Board

February 28, 2017

(Via email and Certified Mail)
CERTIFIED MAIL
NO. 7015 1520 0001 8017 1764

Mr. Tom Bruce
Director of Facilities
Hazel Hawkins Hospital
911 Sunset Drive
Hollister California, 95023
tbruce@hazelhawkins.com

**SUBJECT: NOTICE OF VIOLATION; UNDERGROUND STORAGE TANK SYSTEM
LOCATED AT HAZEL HAWKINS HOSPITAL, 911 SUNSET DRIVE, HOLLISTER**

Dear Mr. Bruce:

As part of an initiative by the State Water Resources Control Board (State Water Board) to ensure compliance at government-owned and/or operated underground storage tank (UST) facilities in California, the State Water Board staff inspected the UST at your facility on February 22, 2017, pursuant to authority under Health and Safety Code (H&SC), chapter 6.7, section 25289.

The State Water Board has identified the following violations pursuant to H&SC, chapter 6.7, and California Code of Regulations (CCR), title 23, chapter 16:

No.	Violation	Tank	Start Date	Stop Date	Regulation
1	Failure to Maintain Site Map On-Site – Site map does not contain product piping or reference the UST piping and auxiliary equipment with respect to buildings or street.	Diesel	February 22, 2017	Ongoing	23 CCR 2711(a)(8)
2	Failure to Perform Designated Operator (DO) Inspections – The DO report for October 2016 was not present at time of inspection.	Diesel	September 30, 2016	November 1, 2016	23 CCR 2715(c)
3	Failure to Provide DO Training – The DO training documentation was not observed at time of inspection. DO training documents were emailed on February 22, 2017.	Diesel	February 22, 2017	February 22, 2017	23 CCR 2715(f)

No.	Violation	Tank	Start Date	Stop Date	Regulation
4	Failure to Maintain Financial Responsibility On-Site – Certificate of Financial Responsibility is not available in CERS and was not available at the time of inspection.	Diesel	February 22, 2017	Ongoing	23 CCR 2712(i)
5	Failure to Maintain Monitoring Plan – The Monitoring Plan indicates in the Pipe Monitoring section that the Piping Secondary Containment is “dry,” but it should indicate “wet.”	Diesel	February 22, 2017	Ongoing	H&SC 25286(a); 23 CCR 2632(d)(1)

You are directed to correct the ongoing violations and submit compliance documentation to the State Water Board and San Benito County Health Department within sixty (60) days from the date of this letter. Have your Designated Operator make specific notations in the next monthly designated operator report indicating the ongoing violations have been corrected. The monthly designated operator report and any associated photos must be submitted as proof of compliance.

Please send all compliance documentation to the following:

State Water Board

Rebecca Green
UST Enforcement Unit
Office of Enforcement
State Water Resources Control Board
801 K Street, Suite 2300
Sacramento, California 95814
rebecca.green@waterboards.ca.gov

Local CUPA

Ms. Olga Vargas
Environmental Health Specialist
San Benito County Health Department
1111 San Felipe Road, Suite 102
Hollister, California, 95023
ovargas@cosb.us

Pursuant to Health and Safety Code, chapter 6.7, section 25299, the owner and operator of the tank(s) are liable for a penalty of \$500 to \$5,000 per tank, per day of violation. These penalties will continue to accrue until the violations have been corrected.

If you have any questions, please contact me at (916) 341-5551, or by email at amantha.henkel@waterboards.ca.gov.

Sincerely,



Amantha Henkel
Senior Environmental Scientist
UST Enforcement Unit
Office of Enforcement

cc: See next page.

cc: *(via email only)*

Ms. Olga Vargas
Environmental Health Specialist
San Benito County Health Department
ovargas@cosb.us